

**ExxonMobil Refining & Supply Company**  
Global Remediation

4096 Piedmont Avenue #194  
Oakland, California 94611  
510.547.8196  
510.547.8706 Fax  
jennifer.c.sedlachek@exxonmobil.com

**Jennifer C. Sedlachek**  
Project Manager

**ExxonMobil**  
*Refining & Supply*

February 24, 2006

Mr. Chris Murray  
Subregional Water Management System  
Industrial Waste Section  
4300 Llano Road  
Santa Rosa, California 95407


**RE: Former Exxon RAS #7-3035/4501 Sonoma Highway, Santa Rosa, California.**

Dear Mr. Murray:

Attached for your review and comment is a copy of the letter report entitled *Quarterly Self-Monitoring Report*, dated February 24, 2006, for the above-referenced site. The report was prepared by Environmental Resolutions, Inc. (ERI) of Petaluma, California, and details remedial activities for the subject site.

If you have any questions or comments, please contact me at 510.547.8196.

Sincerely,


A handwritten signature in black ink, appearing to read 'J. Sedlachek', followed by the word 'FOR' in capital letters.

Jennifer C. Sedlachek  
Project Manager

Attachment: ERI's Quarterly Self-Monitoring Report, dated February 24, 2006.

cc: w/ attachment  
Ms. Jo Bentz, California Regional Water Quality Control Board, North Coast Region

w/o attachment  
Ms. Paula Sime, Environmental Resolutions, Inc.



**ENVIRONMENTAL RESOLUTIONS, INC.**

## TRANSMITTAL

TO: Mr. Chris Murray  
Subregional Water Management System  
4300 Llano Road  
Santa Rosa, California 95407

DATE: February 27, 2006  
PROJECT NUMBER: 200303X  
SUBJECT: Former Exxon Service Station 7-3035,  
4501 Sonoma Highway, Santa Rosa, California.

FROM: Paula Sime  
TITLE: Project Manager

WE ARE SENDING YOU:

COPIES	DATED	DESCRIPTION
1	February 24, 2006	Quarterly Self-Monitoring Report

THESE ARE TRANSMITTED as checked below:


☐ For review and comment    ☐ Approved as submitted    ☐ Resubmit \_\_ copies for approval  
☐ As requested    ☐ Approved as noted    ☐ Submit \_\_ copies for distribution  
☒ For approval    ☐ Return for corrections    ☐ Return \_\_ corrected prints  
☐ For your files    ☒ Sign and return

REMARKS: At the request of Exxon Mobil Corporation (Exxon Mobil), Environmental Resolutions, Inc. (ERI) is sending you the above-referenced document. Please call Paula Sime at (707) 766-2000 if you have any questions.

**SCANNED**

*Paula Sime*  
\_\_\_\_\_  
Paula Sime, Project Manager

cc: Ms. Jo Bentz, California Regional Water Quality Control Board, North Coast Region  
Ms. Jennifer C. Sedlachek, ExxonMobil Refining & Supply – Global Remediation  
ERI Project File 200303X



**ENVIRONMENTAL RESOLUTIONS, INC.**

---

February 24, 2006  
ERI 200311CM.L75

Ms. Jennifer C. Sedlachek  
ExxonMobil Refining & Supply – Global Remediation  
4096 Piedmont Avenue #194  
Oakland, California 94611

**SUBJECT**      Quarterly Self-Monitoring Report  
Former Exxon Service Station 7-3035  
4501 Sonoma Highway, Santa Rosa, California

**City of Santa Rosa Industrial User Permit No. SR-GW6100**

Ms. Sedlachek:

At the request of Exxon Mobil Corporation (Exxon Mobil), Environmental Resolutions, Inc. (ERI) is submitting this Quarterly Self Monitoring Report documenting the operational status of the groundwater extraction and treatment (GET) system at the subject site during the first quarter 2006. ERI is submitting this report in compliance with the requirements of the discharge permit set forth by the Santa Rosa Subregional Wastewater Management System (the City).

The GET system did not operate during the first quarter 2006. The system was shut down on August 25, 2005, for repairs to the two rotary vane extraction blowers. The system will remain shut down pending redesign.

The system did not operate during the reporting period; therefore, samples were not collected and associated laboratory analytical results and Critical Parameters Report forms are not included in this submittal.

## **DOCUMENT DISTRIBUTION**

ERI recommends forwarding a copy of this report to:



Mr. Chris Murray  
Subregional Water Management System  
Industrial Waste Section  
4300 Llano Road  
Santa Rosa, California 95407

Ms. Jo Bentz  
California Regional Water Quality Control Board  
North Coast Region  
5550 Skylane Boulevard, Suite A  
Santa Rosa, California 95403

February 24, 2006

Please contact Ms. Paula Sime, ERI's project manager for this site, at (707) 766-2000 with any questions regarding this submittal.

Sincerely,  
Environmental Resolutions, Inc.

  
**SCANNED  
IMAGE**  
Matthew T. Herman  
Senior Staff Engineer  


Paula Sime  
Project Manager